03500.015750.1 PE 405 BE



**PATENT** 

# IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of:	)	
	:	Examiner: Raquel Y. Gordon
KYOTA MIYAZAKI ET AL.	)	
1 1 1 N 10/661 600	:	Group Art Unit: 2853
Application No.: 10/661,683	)	11 C D / ( ) 1
Filed: September 15, 2003	:	U.S. Patent No.: 6,896,359 B1
rned. September 13, 2003	<i>)</i>	Issued: May 24, 2005
For: INK JET RECORDING HEAD AND	,	133ucu. 1viay 24, 2003
METHOD FOR MANUFACTURING INK	:	
JET RECORDING HEAD	)	October 21, 2005
	•	•

COMMISSIONER FOR PATENTS P.O. Box 1450 Alexandria, Virginia 22313-1450

ATTENTION: CERTIFICATES OF CORRECTION BRANCH

# REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050), in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

10/24/2005 HLE333 00000069 6896359 01 \*C:1811 100.00 GP

•

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Attorney for Patentees

Douglas W. Pinsky

Registration No. 46,994

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

desimine: (212) 21

DWP/gmc

DC Main 197447v1

# UNITED STATES PATENT AND TRADEMARK OFFICE

# **CERTIFICATE OF CORRECTION**

PATENT NO.

6,896,359 B1

DATED

May 24, 2005

INVENTOR(S) :

KYOTA MIYAZAKI ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

### COLUMN 1

Line 13, "me hod" should read --method--.

### COLUMN 2

Line 46, "10a" should read --101a--.

### COLUMN 5

Line 52, "port's" should read --ports--.

# **COLUMN 8**

Line 54, "to 10," should read -- to 10C,--.

**MAILING ADDRESS OF SENDER:** 

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

PATENT NO. 6,896,359 B1

No. of add'l. copies @ 30¢ per page



# PRINTER'S TRIM LINE

# UNITED STATES PATENT AND TRADEMARK OFFICE

# **CERTIFICATE OF CORRECTION**

PATENT NO.

6,896,359 B1

**DATED** 

May 24, 2005

INVENTOR(S) :

KYOTA MIYAZAKI ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## **COLUMN 1**

Line 13, "me hod" should read --method--.

#### COLUMN 2

Line 46, "10a" should read --101a--.

### **COLUMN 5**

Line 52, "port's" should read --ports--.

### COLUMN 8

Line 54, "to 10," should read --to 10C,--.

### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,896,359 B1

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82)